

## **Appendix 1 – Photographs**



Photograph 1- Kuala Tripa Hotel, Banda Aceh. An example of a soft storey.  
Refer Recommendation No. 16.



Photograph 2- Reinforced concrete building, Banda Aceh. An example of poor beam-column joints. Refer Recommendation Nos. 10 & 19.



Photograph 3- Confined brick masonry building, Banda Aceh. When walls collapsed practical columns were overloaded. Refer Recommendation Nos. 15 & 18.



Photograph 4- Reinforced concrete building, Banda Aceh. Ties are too small and too widely spaced. Column has failed. Refer Recommendation No. 19.



Photograph 5- Reinforced concrete Hotel, Banda Aceh. Failure of beam column joints.  
Refer Recommendation Nos. 10 & 19.



Photograph 6- Typical Building, Banda Aceh. Failure of heavy architectural elements.  
Refer Recommendation No. 14.



Photograph 7- Reinforced concrete moment resisting frame building, Banda Aceh.  
Failure of beam column joints. Refer Recommendation Nos. 10 & 19.  
Failure of infill wall panels. Refer Recommendation No. 15.